

Health and Safety

Area Satisfactory Check	25/26
Asbestos (is missing?)	100%
Electric	97.8%
Fire	86.7%
Gas	100%
Water/Legionella	100%
Lift	100%